



序号	报告编号	受检单位名称	受检单位地址	受检单位联系人	现场检测人员	检测日期	报告签发日期	现场检测图像
1	JSGR(R)JC20241032	京口区雅美口腔诊所	镇江市京口区南门大街 252 号	严妍	陈天乐、于小盼	2024.8.26	2024.9.25	
2	JSGR(R)JC20241033	南京高淳中彭口腔门诊部	南京市高淳区古柏街道茅山路商业街 2 栋 103、203	徐建英	陈天乐、于小盼	2024.8.26	2024.9.25	

3	JSGR(R)JC20241088	兴化瑞慈骨科医院	兴化市临城街道五里西路 33 号	钱银河	陈天乐、于小盼	2024.9.9	2024.9.28	
4	JSGR(R)JC20241090 JSGR(R)JC20241091	兴化城南医院	兴化市丰收南路 410 号	刘广武	陈天乐、于小盼	2024.9.9	2024.9.28	 
5	JSGR(R)JC20241109 JSGR(R)JC20241110 JSGR(R)JC20241111	泰兴市新街镇卫生院 泰兴市农产品加工园区医院	泰兴市农产品加工园 区纬二路 1 号	/	陈天乐、于小盼	2024.9.14	2024.9.23	

								 A white medical X-ray machine with a large circular tube and a control panel with various buttons and a small screen. It is positioned over a blue padded table.  A white CT scanner machine with a circular opening. A patient's arm is visible inside the machine, which is covered with a blue protective sheet.
6	JSGR(R)JC20241126 JSGR(R)JC20241127	兴化市海南镇卫生院	兴化市海南镇文昌路东首	许院长	陈天乐、于小盼	2024.9.19	2024.9.27	 A control room with multiple computer monitors displaying medical images. There is a printer, a keyboard, and other office equipment on the desk.

								
7	JSGR(R)JC20241128	兴化市多乐口腔诊所	兴化市安丰镇北环路 新天地广场一层商铺 45号	郝聪美	陈天乐、于小盼	2024.9.19	2024.9.26	
8	JSGR(R)JC20241129 JSGR(R)JC20241130	兴化市安丰镇中心 卫生院分院(中圩)	兴化市安丰镇中圩村 振中路 185 号	薛宝明	陈天乐、于小盼	2024.9.19	2024.9.24	

								
9	JSGR (R) JC20241136 JSGR (R) JC20241137 JSGR (R) JC20241138	泰州市姜堰区溱潼镇沈高卫生院	泰州市姜堰区溱潼镇河横村春蕾路	许霁	陈天乐、于小盼	2024.9.23	2024.9.26	

								
10	JSGR(R)JC20241165	姜堰阳光口腔诊所	姜堰区通扬路 146-5、146-6 号	周小锋	陈天乐、于小盼	2024.8.30 2024.9.12	2024.9.28	
11	JSGR(R)JC20241185	医药高新福因口腔门诊部	泰州市海陵南路 199 号周山汇水花园 7 幢 120 室	秦鑫隆	陈天乐、于小盼	2024.9.29	2024.9.29	